

Western Plastics

MATERIAL SAFETY DATA SHEET

--- SECTION I ---

IDENTITY: Yellow Spaghetti Mat™

MANUFACTURER'S NAME AND ADDRESS

EMERGENCY TELEPHONE NOS.

GREENSTREAK GROUP INC.  
3400 Tree Court Industrial Blvd.  
St. Louis, Mo. 63122

Weekdays: (636) 861-2600 x 211  
Fax: (636) 861-5980  
MSDS Information (636) 861-2600 x 211

Date Prepared: 08/22/02

Signature of Preparer: BDC

--- SECTION II – HAZARDOUS INGREDIENTS –

HAZARDOUS COMPONENTS AMT – OSHA PEL – ACGIH TLV – OTHER LMST – CAS #

--NONE --

--SECTION III – PHYSICAL DATA ---

Boiling Point: Solid

Vapor Pressure: Solid

Vapor Density: Solid

Specific Gravity: 1.37

Melting Point: 350°F

Evap. Rate: Solid

Solubility in Water: None

Appearance and Odor: Coils of extruded plastic – no specific odor.

--- SECTION IV – FIRE AND EXPLOSION HAZARD DATA ---

Flash Point: N/A Flammable Limits:

Extinguishing Media: Self extinguishing, water spray, CO<sub>2</sub>, dry chemical

Special Fire Fighting Procedures: When fighting fire in confined area, self contained breathing apparatus should be worn.

Unusual Fire and Explosion Hazards: P.V.C. evolves Hydrogen Chloride, carbon monoxide and other toxic gases when burned. Confined exposure to extremely high concentration of combustion products may be fatal and should be avoided.

--- SECTION V – REACTIVITY DATA ---

Stability: Stable

Hazardous Decomposition or Byproducts: Hydrogen Chloride, Carbon Monoxide, Carbon Dioxide

--- SECTION VI – HEALTH HAZARD DATA –

None

--- SECTION VII PRECAUTIONS FOR SAFE HANDLING AND USE –

Steps to be Taken in Case Material is Released or Spilled:

Solid – Pick it Up

Waste Disposal Method – Send to Sanitary Land Fill, no special precautions.

Precautions to Be Taken in Handling and Storing – Under normal handling & use conditions there is no hazard to health. When fusion welding field splices work in ventilated area.

-- SECTION VIII – CONTROL MEASURE ---

Respiratory Protection – Fumes from Molten Plastic should not be breathed unnecessarily.

Ventilation – Local Exhaust – ventilate when fabrication (fusion welding) in confined areas.

Other Protective Clothing or Equipment – Self – Contained breathing apparatus if fusion welding in non-ventilated confined areas.